DATE:	·		OR S.N.		
<del></del> -	6.18.02	FROM:	Œ.		(print name)
		REASON(S):			**
FORWARD T		A. You had Pa	rent	(check box)	
A. Art Unit:	2185	B. See Title	<i>i</i>	(check box)	
B. Class:	<u>-712</u>	C. See Abstrac	ot '	(check box)	
C Subclass:	500+	D. See Claim(s	5):		
FURTHER EX	(PLANATION IF NEE	DED:			
	Clock d	rich end inter	n system		
DATE:	10/8/02	FROM:	CAO		(print name)
		REASON(S):			
FORWARD T	O:	A. You had Pa	rent	(check box)	
A. Art Unit:	2812	B. See Title		(check box)	
B. Class:	438	C. See Abstrac	zt .	(check bax)	
C Subclass:		D. See Claim(	s):		· · · · · · · · · · · · · · · · · · ·
	(PLANATION IF NEE	DED:			
	Semicondut	to device	curui	ary	
DATE:	10/2/2	FROM:	Thie	blig	(print name)
		REASON(S):		·	
FORWARD T	O CLASSIFIER	A. You had Pa	rent	(check box)	
		B. See Title		(check box)	
		C. See Abstra	ct	(check box)	
		D. See Claim(	s):		
FURTHER EX	KPLANATION IF NEE	DED:	,	1	00438
No	method	of mal	nng o	livre f	1 0 1 7 0
	ON BY 2700 CLA				
DATE:		CLASSIFIER:			
	,	REASON(S):			
FORWARD T	·O:	A. You had Pa	rent	(check box)	
A. Art Unit:		B. See Title		(check box)	
B. Class:		C. See Abstra	ct	(check box)	
C Subclass:		D. See Claim(	(s):		
C CUUCIDO.	VOLAMATION IE NEE	<u> </u>			
		.000.	ant col	Le in class	757 _
	of a comic	nductor d	evice to	be in come	20/ 112
	of a semice	nductor d	n class	#438, to	much for 3
	of a semice	nductor d	n class	#438, to	much for 3
	of a semice nufacturing mining & proce clas	nductor d to be in	n class Fracti	100 al -N-1	much for 3 nogrammiy ngnal.